

INSPECTION REPORT (検品書)

SERIAL NUMBER (号機) : 903B-W8D00303	9671 HR
ENGINE NO. (エンジン号機) : S3Q2	YR
EMISSION REGULATION (排ガス規制) : TIER 3 EMISSION STANDARDS 3次排ガス	km
Tire Size (タイヤサイズ) : 15.5 / 60 - 18 8P.R	EPA: WITH / WITHOUT

項目	評価	メモ	項目	評価	メモ
ENGINE エンジン			TIRE タイヤ		
Main Engine <エンジン本体>	C		Front Right Tire <右前輪>	C	
Head Cover <ヘッドカバー>	C		Front Left Tire <左前輪>	C	
Sound <音>	C		Rear Right Tire <右後輪>	C	
Exhaust Pressure <排圧>	C		Rear Left Tire <左後輪>	C	
Exhaust Color <排気色>	C		OUT LOOKING 外観		
Muffler Body <マフラー本体>	C		Bucket <バケット>	C	
Radiator <ラジエター>	C		Lift Arm <リフトアーム>	C	
Oil Cooler <オイルクーラー>	C		Looseness of center pin <センターピンガタ>	D	LOOSE ガタ
MAIN PUMP ポンプ			Front Axle <フロントアクスル>	C	
Oil Leaking <オイル漏れ>	C		Rear Axle <リアアクスル>	C	
Sound <音>	C		Wheel Rim <ホイールリム>	C	
Power <パワー>	C		Frame <フレーム>	C	
Contol Valve <コントロールバルブ>	C		Tanks&Covers <タンク・カバー類>	C	
Hose/Pipe etc. <ホース/配管類>	C		Mud Guard <フェンダー類>	C	
OPERATION SYSTEM 操縦関係			Step <ステップ>	C	
Running <走行>	C		Paint <塗装>	C	
Main Clutch / Torque Converter <メインクラッチ/トルコン>	C		HYD.CYLINDER シリンダー関係		
Transmission <トランスミッション>	C		Lift Cylinder <リフトシリンダー>	C	
Propeller Shaft <プロペラシャフト>	C		Dump Cylinder <ダンプシリンダー>	C	
Steering / Power Steering <ステアリング/ パワステ>	C		Steering Cylinder <ステアリングシリンダー>	C	
Brake <ブレーキ>	C		OTHER 付属部品		
INTERIOR キャビン内装			Battery <バッテリー>	GOOD / FLAT	
Cabin Appearance <キャビン外観>	C		Ride Control System <ライドコントロール>	WITH / WITHOUT	
Glass <ガラス>	C				
Operator Seat <シート>	C	RIPPED 破れ			
Floor Mat <フロアマット>	C				
Monitor <モニター>	C				
Air-Cond. <エアコン>	C				
Operation Lever <操作レバー>	C				
Pedal <ペダル>	C				

A: replaced with brand new or rebuilt parts B: in good working condition considering its age C: normal operation; appears worn and deterioration
D: operational, but need repairs E: need quick repairs or replacement parts
A: 新品または再生品 B: 経年に比例して良好 C: 稼働に異常は無いが経年相当の摩耗・劣化あり
D: 稼働はするが修理が必要 E: 即修理をしないと稼働しない

*We described this inspection report based on our judgement and view. We do not guarantee the condition shown on this inspection report.
*この検品書は私どもの見解判断に基づいて作成したものであり、機械の程度を保証するものではありません。