

INSPECTION REPORT (検品書)

SERIAL NUMBER (号機) : T2-TTS4-21662	5057 HR
ENGINE NO. (エンジン号機) : 6BG1-132682	1994 YR
EMISSION REGULATION (排ガス規制) : TIER 1 EMISSION STANDARDS 1次排ガス	21461 km
Tire Size (タイヤサイズ) : 14/70-20 12PLY	EPA: WITH / <u>WITHOUT</u>
ROLLER TYIP : TIRE ROLLER / COMBINED ROLLER / TANDEM ROLLER / MACADAM ROLLER / VIBRATION ROLLER	

項目	評価	メモ	項目	評価	メモ
ENGINE エンジン			TIRE タイヤ		
Main Engine <エンジン本体>	C		Front Tire <前輪>	C	CRACK 亀裂
Head Cover <ヘッドカバー>	C		Rear Tire <後輪>	C	CRACK 亀裂
Sound <音>	C		OUT LOOKING 外観		
Exhaust Pressure <排圧>	C		Front Axle <フロントアクスル>		
Exhaust Color <排気色>	C		Rear Axle <リアアクスル>	C	
Muffler Body <マフラー本体>	B		Wheel Rim <ホイールリム>	C	
Radiator <ラジエター>	B		Frame <フレーム>	B	
Oil Cooler <オイルクーラー>			Tanks&Covers <タンク・カバー類>	C	RUSTY さび
OPERATION SYSTEM 操縦関係			Mud Guard <フェンダー類>		
Running <走行>	C		Step <ステップ>	B	
Main Clutch / Torque Convertor <メインクラッチ/トルコン>	C		Paint <塗装>	C	RUSTY さび
Transmission <トランスミッション>	C		HYD.CYLINDER シリンダー関係		
Propeller Shaft <プロペラシャフト>	C		Steering Cylinder <ステアリングシリンダー>	C	LITTLE OIL LEAK オイル滲み
Steering / Power Steering <ステアリング/ パワステ>	C		OTHER 付属部品		
Brake <ブレーキ>	C		Battery <バッテリー>		<u>GOOD</u> / FLAT
Vibration <バイブレーション>					
INTERIOR キャビン内装					
Cabin Appearance <キャビン外観>	C	CNP			
Glass <ガラス>					
Operator Seat <シート>	B				
Floor Mat <フロアマット>					
Monitor <モニター>	C				
Air-Cond. <エアコン>					
Operation Lever <操作レバー>	C	LEVER KNOB MISSING 前後進レバーのノブ欠品			
Pedal <ペダル>	C				

A: replaced with brand new or rebuilt parts B: in good working condition considering its age C: normal operation; appears worn and deterioration
D: operational, but need repairs E: need quick repairs or replacement parts
A: 新品または再生品 B: 経年に比例して良好 C: 稼働に異常は無いが経年相当の摩耗・劣化あり
D: 稼働はするが修理が必要 E: 即修理をしないと稼働しない

*We described this inspection report based on our judgement and view. We do not guarantee the condition shown on this inspection report.
*この検品書は私どもの見解判断に基づいて作成したものであり、機械の程度を保証するものではありません。